Oil Field Environmental Incident Summary

Incident: 20150725195148 **Date/Time of Notice:** 07/25/2015 19:51

Responsible Party: CONTINENTAL RESOURCES, INC. CONTINENTAL RESOURCES, INC.

Well Name: LIMOUSIN 1-3H

Field Name: SANISH Well File #: 26391

Date Incident: 7/25/2015 Time Incident: 12:00 Facility ID Number: **MOUNTRAIL** Twp: 152 **Rna**: 93 **Sec:** 3 County:

Location Description:

Submitted By: Shane Knuchel Received By:

Contact Person: Shane Knuchel

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

> Spilled **Units** Recovered Units Followup **Units** 5 gallons

Gallons Oil 10

Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/1/2015 Clean Up Concluded: 7/26/2015

Risk Evaluation:

None

Areal Extent:

1/2 gallon was released off west side of location. Approximately 180x180 ft area.

Page 1 of 3

Potential Environmental Impacts:

Topsoil, vegetation.

Action Taken or Planned:

Misted vegetation will be mowed and bagged. Equipment will be power washed, and location bladed.

Wastes Disposal Location: Prairie Disposal

Agencies Involved: Notified Ashleigh Day NDIC by phone on 7/25/2015 at 2:20 PM CT.

Notified Army Corps of Engineers at 2:49 PM CT on 7/25/2015.

Updates

Date: 7/27/2015 Status: Reviewed - Follow-up Required Author: Suess, Bill

Updated Oil Volume: 10.00 gallons

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Although released amount was small, the release did leave the well pad. Due to the proximilty to Lake Sakakawea, followup is necessary.

Date: 9/1/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 14:30 9/1/2015.

Minimal impacts to the areas off of location. Absorbent socks and pom poms are in low areas and drainages that run off cliff into Lake Sakakawea. Remediation is complete at the time of inspection.

No followup is necessary.

Date: 9/1/2015 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Cleanup report submitted. Laboratory data indicates that remediation was successful. No additional work is warranted.

Date: 3/10/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 10, 2016.